

C.O.C.: G105017/105018

REPORT No. B22-25852

Report To:

PSLL

3 Chm. Colins,
Val Des Monts QC J8N 6G1 Canada

Attention: Richard Bourassa

Caduceon Environmental Laboratories

2378 Holly Lane
Ottawa Ontario K1V 7P1
Tel: 613-526-0123
Fax: 613-526-1244

DATE RECEIVED: 15-Aug-22

JOB/PROJECT NO.: Lac Chevreuil - Lake Water E-coli

DATE REPORTED: 16-Aug-22

P.O. NUMBER:

SAMPLE MATRIX: Surface Water

WATERWORKS NO.

Parameter			E coli				
Units			cfu/100mL				
R.L.			1				
Reference Method			MOE E3371				
Date Analyzed/Site			15-Aug-22/O				
Client I.D.	Sample I.D.	Date Collected					
Lac Chevreuil CH1	B22-25852-1	14-Aug-22	0				
Lac Chevreuil CH2	B22-25852-2	14-Aug-22	0				
Lac Chevreuil CH3	B22-25852-3	14-Aug-22	0				
Lac Chevreuil CH4	B22-25852-4	14-Aug-22	1				
Lac Chevreuil CH5	B22-25852-5	21-Aug-22	1				



Shelly Lozo

Microbiology Analyst

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from