

C.O.C.: G105016

REPORT No. B22-25841

Report To:

PSLL

3 Chm. Colins,
Val Des Monts QC J8N 6G1 Canada

Attention: Richard Bourassa

Caduceon Environmental Laboratories

2378 Holly Lane
Ottawa Ontario K1V 7P1
Tel: 613-526-0123
Fax: 613-526-1244

DATE RECEIVED: 15-Aug-22

JOB/PROJECT NO.: Lac Louise - Lake Water Ecoli

DATE REPORTED: 16-Aug-22

P.O. NUMBER:

SAMPLE MATRIX: Surface Water

WATERWORKS NO.

Parameter			E coli				
Units			cfu/100mL				
R.L.			1				
Reference Method			MOE E3371				
Date Analyzed/Site			15-Aug-22/O				
Client I.D.	Sample I.D.	Date Collected					
Lac Louise L1	B22-25841-1	14-Aug-22	5				
Lac Louise L2	B22-25841-2	14-Aug-22	0				
Lac Louise L3	B22-25841-3	14-Aug-22	1				
Lac Louise L4	B22-25841-4	14-Aug-22	1				
Lac Louise L5	B22-25841-5	14-Aug-22	0				
Lac Louise L6	B22-25841-6	14-Aug-22	0				
Lac Louise L7	B22-25841-7	14-Aug-22	0				
Lac Louise L8	B22-25841-8	14-Aug-22	0				
Lac Louise L9	B22-25841-9	14-Aug-22	1				
Lac Louise L10	B22-25841-10	14-Aug-22	0				
Lac Louise L11	B22-25841-11		1				



Shelly Lozo

Microbiology Analyst

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from